

# X-AM 8000 STANDUP BASE P/N 8325874



- Use to stand instrument up for easy viewing during area or confined space monitoring.
- For use with X-am 8000 or optionally with X-am 3500.
- To use with the X-am 3500 the following items are needed:
  - 8326823 Shoulder strap with buckle
  - 8326819 Spare Set Bow for belt fastening
  - 8326824 Label Holder (optional)

