

CALIBRATION ADAPTER, PAC III

P/N 6806291

- Directs flow of calibration gas directly towards the sensors
- Does not absorb reactive chemicals detected by the Pac III Sensors (see appropriate sensor data sheet)
- Includes:
 - Cal Adapter
 - 2 white barb connectors
 - 3 ft. of viton hose

